
Contents

| | |
|-----------------------------------------------------------------------------------|--------------|
| List of Figures | xiii |
| List of Tables | xix |
| Preface | xxiii |
| Author Bios | xxv |
| 1 Strategies for Experimentation with Multiple Factors | 1 |
| 1.1 Introduction | 1 |
| 1.2 Some Definitions | 2 |
| 1.3 Classical Versus Statistical Approaches to Experimentation | 3 |
| 1.4 Why Experiment? (Analysis of Historical Data) | 6 |
| 1.5 Diagnosing the Experimental Environment | 7 |
| 1.6 Example of a Complete Experimental Program | 9 |
| 1.6.1 Chemical Process System | 9 |
| 1.6.2 Step One: Screening | 9 |
| 1.6.3 Step Two: Crude Optimization | 11 |
| 1.6.4 Step Three: Final Optimization | 12 |
| 1.7 Good Design Requirements | 13 |
| 1.8 Summary | 15 |
| 1.8.1 Important Terms and Concepts | 15 |
| 2 Statistics and Probability | 17 |
| 2.1 Introduction | 17 |
| 2.2 Graphical and Numerical Summaries of a Single Response-Variable | 18 |
| 2.2.1 Dot Diagrams | 18 |
| 2.2.2 Sample Mean, Variance, and Standard Deviation | 18 |
| 2.2.3 Histograms | 20 |
| 2.2.4 Five-Number Summaries and Boxplots | 22 |
| 2.3 Graphical and Numerical Summaries of the Relation Between Variables | 25 |
| 2.4 What to Expect from Theory | 27 |
| 2.4.1 Probability Density Functions and Probability | 27 |
| 2.4.2 Expected Values, Variance, and Standard Deviation | 28 |
| 2.4.3 Normal Distribution | 31 |
| 2.4.4 Central Limit Theorem and Distribution of Sample Means | 32 |
| 2.5 Using Theory to Help Interpret Experimental Data | 36 |
| 2.5.1 Comparing the Mean of Experimental Results to a Standard | 36 |
| 2.5.2 Comparing the Means of Two Experimental Conditions | 38 |
| 2.5.3 Comparing the Means of Several Experimental Conditions | 39 |

| | | |
|----------|-------------------------------------------------------------------------------------|-----------|
| 2.5.4 | Comparing Observed Data to the Normal Distribution | 43 |
| 2.6 | Summary | 46 |
| 2.6.1 | Important Equations | 46 |
| 2.6.2 | Important Terms and Concepts | 47 |
| 2.7 | Exercise | 47 |
| 3 | Basic Two-Level Factorial Experiments | 49 |
| 3.1 | Introduction | 49 |
| 3.2 | Two-Level Factorial Design Geometry | 50 |
| 3.3 | Main Effect Estimation | 52 |
| 3.4 | Interactions | 54 |
| 3.5 | General 2^k Factorial Designs | 56 |
| 3.6 | Randomization | 58 |
| 3.7 | Example of a 2^3 Factorial Experiment | 59 |
| 3.7.1 | Background and Design | 59 |
| 3.7.2 | Calculation of Effects and Interactions | 61 |
| 3.8 | Significance of Effects and Interactions | 63 |
| 3.8.1 | Statistical Significance of Results | 63 |
| 3.8.2 | Pooled Variance | 64 |
| 3.8.3 | Statistical Significance of Results for Fly Ash | 66 |
| 3.8.4 | Interpretation of Results for Fly Ash Example | 67 |
| 3.8.5 | Example of Computer Analysis of Data | 68 |
| 3.9 | Example of an Unreplicated 2^4 Design (Stack Gas Treatment) | 70 |
| 3.9.1 | Background and Design | 70 |
| 3.9.2 | Graphical Analysis | 71 |
| 3.9.3 | Numerical Analysis | 73 |
| 3.9.4 | Interpretation of Results | 75 |
| 3.10 | Judging Significance of Effects When There Are No Replicates | 76 |
| 3.11 | Summary | 79 |
| 3.11.1 | Analysis of 2^k Experiments | 79 |
| 3.11.2 | Important Equations | 80 |
| 3.11.3 | Important Terms and Concepts | 80 |
| 3.12 | Exercise | 81 |
| 4 | Additional Tools for Two-Level Factorials | 83 |
| 4.1 | Introduction | 83 |
| 4.2 | Number of Replicates Needed for Desired Precision | 83 |
| 4.3 | Results in Equation Form | 88 |
| 4.4 | Testing for Curvature | 91 |
| 4.5 | Blocking Factorial Experiments | 96 |
| 4.5.1 | Calculating the Error of an Effect (s_E) in Blocked 2^k Experiments | 98 |
| 4.5.2 | Two Block Example | 99 |
| 4.5.3 | Designs for Blocked Factorials | 101 |
| 4.6 | Split-Plot Designs | 102 |
| 4.6.1 | Split-Plot Example | 104 |
| 4.6.2 | Designs for Split-Plot 2^k Experiments | 108 |
| 4.7 | Summary | 108 |
| 4.7.1 | Important Equations | 109 |
| 4.7.2 | Important Terms and Concepts | 110 |

| | |
|---------------------------------------------------------------------------------------------------------------------|------------|
| 4.8 Exercises | 110 |
| 5 General Factorial Experiments and ANOVA | 113 |
| 5.1 Introduction | 113 |
| 5.2 Multiple Level Factorial Designs | 114 |
| 5.3 Mathematical Model for Multiple Level Factorials | 115 |
| 5.4 Testing the Significance of Main Effects and Interaction Effects | 118 |
| 5.5 Example of a Multilevel Two-Factor Factorial | 119 |
| 5.6 Comparison of Means after the ANOVA | 123 |
| 5.6.1 The Least Significant Difference (LSD) Method | 123 |
| 5.6.2 Tukey's Method of Comparing Means after the ANOVA | 124 |
| 5.6.3 Orthogonal Contrasts | 125 |
| 5.6.4 Other Applications of Orthogonal Contrasts | 128 |
| 5.6.4.1 Orthogonal Polynomial Contrasts | 128 |
| 5.6.4.2 Analysis of Unreplicated Multilevel Factorials | 129 |
| 5.7 Analysis of Blocked and Split-Plot Factorial Experiments with Multilevel Factors | 133 |
| 5.7.1 Analysis of a Blocked Factorial by ANOVA | 134 |
| 5.7.2 Analysis of a Split Plot Factorial by ANOVA | 135 |
| 5.8 Summary | 136 |
| 5.8.1 Important Equations | 136 |
| 5.8.2 Important Terms | 137 |
| 5.9 Exercises | 138 |
| 6 Variance Component Studies | 139 |
| 6.1 Introduction | 139 |
| 6.2 Additivity of Variances | 139 |
| 6.3 Simple Experiments for Estimating Two Sources of Variability | 140 |
| 6.4 Estimation of Variance Components Using ANOVA | 141 |
| 6.5 Graphical Representation of Data from Simple Experiments for Estimating Two Sources of Variability | 143 |
| 6.6 Components of Variance—Multiple Sources | 145 |
| 6.6.1 Introduction | 145 |
| 6.6.2 Nested Designs for Estimating Multiple Components of Variance | 146 |
| 6.7 Staggered Nested Designs | 152 |
| 6.7.1 Design and Analysis with Staggered Nested Designs | 152 |
| 6.7.2 Staggered Nested Design Example with Four Sources | 153 |
| 6.8 Sequential Experimentation Starting With Components of Variation—Case Study | 157 |
| 6.8.1 Introduction | 157 |
| 6.8.2 Staggered Nested Experiment | 158 |
| 6.8.3 Follow-up Split-Plot Experiment | 160 |
| 6.8.4 Conclusions | 163 |
| 6.9 Summary | 164 |
| 6.9.1 Important Equations | 165 |
| 6.9.2 Important Terms | 165 |
| 6.10 Exercises | 165 |

| | | |
|----------|-------------------------------------------------------------------------|------------|
| 7 | Screening Designs | 167 |
| 7.1 | Introduction | 167 |
| 7.2 | Cause-and-Effect Diagrams | 169 |
| 7.3 | Fractionating Factorial Designs | 171 |
| 7.4 | Fractional Factorial Designs | 172 |
| 7.4.1 | Constructing Half Fractions | 174 |
| 7.4.2 | Confounding in Half Fractions | 175 |
| 7.4.3 | Simple Example of a Half Fraction | 177 |
| 7.4.4 | One-Quarter and Higher Fractional Factorials | 178 |
| 7.4.5 | Fractional Factorial Design Tables | 180 |
| 7.4.6 | Example of Fractional Factorial in Process Improvement | 181 |
| 7.4.7 | Advantages of Fractional Factorial Designs | 184 |
| 7.4.8 | Resolution of Fractional Factorial Designs | 187 |
| 7.5 | Plackett–Burman Screening Designs | 188 |
| 7.5.1 | Tables of Plackett–Burman Designs | 189 |
| 7.5.2 | Using the Tables of Plackett–Burman Designs | 190 |
| 7.5.3 | An Example of Using a Plackett–Burman Design | 191 |
| 7.6 | Other Applications of Fractional Factorials | 197 |
| 7.6.1 | Fractional Factorial Designs for Estimating Some Interactions | 197 |
| 7.6.2 | Designs for Blocked Factorials in Fractional Arrangements | 197 |
| 7.7 | Screening Designs with Multiple Level Factors | 200 |
| 7.7.1 | Combination of Factors Method (Pseudofactors) | 201 |
| 7.7.2 | Collapsing Levels (Dummy Levels) | 202 |
| 7.7.3 | L_{18} Orthogonal Array | 202 |
| 7.8 | Summary | 204 |
| 7.8.1 | Important Terms and Concepts | 204 |
| 7.8.2 | Important Formulas | 204 |
| 7.9 | Exercises | 204 |
| 8 | Regression Analysis | 207 |
| 8.1 | Introduction | 207 |
| 8.2 | The Method of Least Squares | 207 |
| 8.2.1 | Estimating the Slope of a Straight Line Through the Origin | 209 |
| 8.3 | Linear Regression | 211 |
| 8.3.1 | Estimating the Slope and Intercept of a Straight Line | 211 |
| 8.3.2 | Statistical Significance of Coefficients | 213 |
| 8.3.3 | Confidence Intervals for Coefficients | 216 |
| 8.3.4 | Precision of Predictions | 219 |
| 8.4 | Multiple Regression | 220 |
| 8.4.1 | Introduction | 220 |
| 8.4.2 | Estimation of Coefficients | 221 |
| 8.4.3 | Statistical Significance of Coefficients | 224 |
| 8.4.4 | Confidence Intervals for Coefficients | 226 |
| 8.4.5 | Precision of Predictions | 227 |
| 8.5 | Quantifying Model Closeness (R^2) | 229 |
| 8.6 | Checking Model Assumptions (Residual Plots) | 231 |
| 8.6.1 | Checking for Normal Distribution of Errors | 232 |
| 8.6.2 | Checking for Constant Variance | 233 |
| 8.6.3 | Checking for Independence of Errors | 234 |

| | | |
|-----------|-------------------------------------------------------------------------------|------------|
| 8.6.4 | Checking for a Mean of Zero for the Errors | 234 |
| 8.7 | Data Transformation for Linearity | 235 |
| 8.8 | Summary | 237 |
| 8.8.1 | Important Equations | 237 |
| 8.8.2 | Important Terms and Concepts | 238 |
| 8.9 | Exercises | 238 |
| 9 | Response Surface Designs | 241 |
| 9.1 | Response Surface Concepts and Methods | 241 |
| 9.2 | Empirical Quadratic Model | 242 |
| 9.3 | Design Considerations | 245 |
| 9.4 | Central Composite Designs | 248 |
| 9.5 | Central Composite Design Example | 251 |
| 9.6 | Graphical Interpretation of Response Surfaces | 255 |
| 9.7 | Other Response Surface Designs | 260 |
| 9.7.1 | Box–Behnken Designs | 260 |
| 9.7.2 | Small Composite Designs | 262 |
| 9.7.3 | Example—Coal Gasification Modeling | 262 |
| 9.8 | Summary | 264 |
| 9.8.1 | Procedure for Design of Experiments for RSM | 264 |
| 9.8.2 | Important Terms and Concepts | 265 |
| 9.9 | Exercises | 266 |
| 10 | Response Surface Model Fitting | 267 |
| 10.1 | Introduction | 267 |
| 10.2 | Estimation of Coefficients in a Quadratic Model | 267 |
| 10.3 | Checking Model Assumptions (Residual Plots) | 270 |
| 10.4 | Statistical Check of Model Adequacy – Lack of Fit (LoF) | 272 |
| 10.5 | Trimming Insignificant Terms from a Model | 274 |
| 10.5.1 | Justification | 274 |
| 10.5.2 | Deleting Statistically Non-Significant Coefficients from Model | 276 |
| 10.6 | Exploring the Response Surface | 279 |
| 10.6.1 | Analytical Interpretation of Response Surfaces | 279 |
| 10.6.2 | Numerical Methods for Interpreting Response Surfaces | 283 |
| 10.7 | Precision of Predictions | 283 |
| 10.8 | Summary | 285 |
| 10.8.1 | General Procedure for Analysis of Data from RSM Design | 285 |
| 10.8.2 | Important Equations | 286 |
| 10.8.3 | Important Terms and Concepts | 286 |
| 10.9 | Exercises | 287 |
| 11 | Sequential Experimentation | 291 |
| 11.1 | Introduction | 291 |
| 11.2 | Augmenting Screening Designs to Resolve Confounding | 292 |
| 11.3 | An Application of Sequential Experimentation in a Process Start-up | 297 |
| 11.4 | Sequential Analysis without Follow-up Experiments | 304 |
| 11.4.1 | Sequential Analysis of Data from a Plackett–Burman Design | 304 |
| 11.4.2 | Sequential Analysis of Screening Designs to Locate Quadratic Optima | 312 |

| | |
|-------------------------------------------------------------------------------|------------|
| 11.5 Summary | 315 |
| 11.5.1 Important Terms and Concepts | 316 |
| 11.6 Exercises | 316 |
| 12 Mixture Experiments | 321 |
| 12.1 Introduction | 321 |
| 12.2 Models for Mixture Problems | 322 |
| 12.2.1 Overview of Modeling | 322 |
| 12.2.2 Slack Variable Models | 323 |
| 12.2.3 Scheffé Models | 324 |
| 12.2.3.1 Scheffé Linear Model | 324 |
| 12.2.3.2 Scheffé Quadratic Model | 324 |
| 12.2.3.3 Scheffé Special Cubic Model | 325 |
| 12.2.3.4 Scheffé Full Cubic Model | 325 |
| 12.3 Experimental Designs for Mixture Problems | 326 |
| 12.3.1 Unconstrained Problems | 326 |
| 12.3.2 An Example | 327 |
| 12.3.3 Constrained Mixture Problems | 329 |
| 12.3.3.1 Pseudo Components | 330 |
| 12.3.3.2 Extreme Vertices Design | 332 |
| 12.4 Data Analysis and Model Fitting for General Constrained Mixture Problems | 335 |
| 12.4.1 Least Squares Model Fitting Examples | 336 |
| 12.4.2 A Procedure for Choosing the Correct Model | 341 |
| 12.4.3 Interpretation of Fitted Models | 341 |
| 12.4.4 Identifying Optimum Conditions | 344 |
| 12.5 Screening Experiments with Mixtures | 345 |
| 12.5.1 Designs for Screening Experiments with Mixtures | 345 |
| 12.5.2 An Example | 350 |
| 12.6 Mixture Experiments with Process Variables | 353 |
| 12.6.1 Designs for Mixture Experiments with Process Variables | 353 |
| 12.6.2 Models for Mixture Experiments with Process Variables | 354 |
| 12.6.3 An Example | 355 |
| 12.7 Summary | 360 |
| 12.8 Exercises | 360 |
| 13 Practical Suggestions for Successful Experimentation | 363 |
| 13.1 Introduction | 363 |
| 13.2 Some Points to Remember | 363 |
| Appendix A | 367 |
| Appendix B | 373 |
| Check Figures for Selected Exercises | 415 |
| Bibliography | 417 |
| Index | 421 |